

February 27 - March 3, 2023
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

2/27/23 – 3/3/23: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
2/27/2023	No Work	Rain	
2/28/2023	No Work	Rain	
3/1/2023	0.029	0.00090	<0.0010
3/2/2023	0.045	0.0019	<0.0010
3/3/2023	0.024	0.0045	<0.00090

NOA reports
posted @

<http://www.rebuildpotrero.com/airmonitoring>

NOA EXCEEDANCES - DETAILS

Date(s): 3/1 – 3/3 – Downwind Monitor

Source: Elevated NOA readings on 3/1 - 3/3 indicated the source of NOA exceedance to be due to excavation related to vertical construction.

Action: Increased water suppression was utilized at the affected monitor area on 3/1 - 3/3 in the vicinity of the affected monitor.

2/27/23 – 3/3/23: PM10 / Dust Weekly REPORT

Dust Monitoring Report
Potrero Phase 2

監測結果
波特雷羅第二階段

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
2/27/2023	Rain - Site Shutdown		
2/28/2023	Rain - Site Shutdown		
3/1/2023	0.007	0.014	0.008
3/2/2023	0.015	0.022	0.017
3/3/2023	0.025	0.015	0.012

NOTE: Upwind monitor was removed from the upwind monitoring station without permission. Potrero monitoring consultants are currently retrieving a replacement upwind monitor

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>

PM-10 Exceedances - Details

Date(s):

Source: None to Report

Action: N/A