

October 24 - October 28, 2022
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

10/24/22 – 10/28/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
10/24/2022	< 0.0010	0.023	0.0010
10/25/2022	0.019	0.014	0.0010
10/26/2022	0.030	0.0037	< 0.00090
10/27/2022	0.0028	0.0037	< 0.0010
10/28/2022	0.020	0.0072	0.0010

NOA reports
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

NOA Exceedances - Details

Date(s): **10/24** – Crosswind Monitor
 10/25-10/26, 10/28 – Downwind Monitor

Source: Elevated NOA readings in the crosswind monitor on 10/24 and downwind monitor on 10/25-10/26 and 10/28 indicated the source of NOA exceedance to be due to earthwork activities related to vertical development.

Action: Increased water suppression was utilized in crosswind and downwind monitor area on 10/24-10/26, and 10/28 in the vicinity of the affected monitors, resulting in lower NOA levels at each respective monitor on subsequent days.

10/24/22 – 10/28/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report Potrero Phase 2

監測結果
波特雷羅第二階段

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全
No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準
Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
10/24/2022	0.012	0.009	0.013
10/25/2022	0.016	0.011	0.020
10/26/2022	0.034	0.018	0.019
10/27/2022	0.017	0.020	0.021
10/28/2022	0.013	0.017	0.016

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>