

**October 31 - November 4, 2022**  
**Weekly Air Monitor Report**  
**Potrero Phase 2 Infrastructure**

## MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

**Note: Any detection above an “action level” is investigated for cause and mitigated.**

# 10/31/22 – 11/4/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc  
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
10/31/2022	0.0010	0.0027	0.0048
11/1/2022	0.013	0.00090	0.0019
11/2/2022	0.020	0.0038	0.00090
11/3/2022	0.0078	0.0019	< 0.0010
11/4/2022	0.0029	0.023	< 0.0010

NOA reports  
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

# NOA Exceedances - Details

**Date(s):**           **11/4** – Crosswind Monitor  
                          **11/2** – Downwind Monitor

**Source:** Elevated NOA readings in the crosswind monitor on 11/4 and downwind monitor on 11/2 indicated the source of NOA exceedance to be due to earthwork activities related to vertical development.

**Action:** Increased water suppression was utilized in crosswind and downwind monitor area on 11/2 and 11/4 in the vicinity of the affected monitors, resulting in lower NOA levels at each respective monitor on subsequent days.

# 10/31/22 – 11/4/22: PM10 / Dust Weekly REPORT

## Dust Monitoring Report Potrero Phase 2

監測結果  
波特雷羅第二階段

*Informe de monitoreo de  
polvo  
Potrero Fase 2*

Clear  $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance  $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM <sub>10</sub> (mg/m <sup>3</sup> )	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
10/31/2022	0.039	0.043	0.049
11/1/2022	0.006	0.008	0.012
11/2/2022	0.009	0.007	0.018
11/3/2022	0.006	0.004	0.010
11/4/2022	0.012	0.013	0.017

Dust Monitoring reports posted 粉塵報告公佈於 @

*Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>*