

AIR QUALITY–NOA REPORT–JULY 2021

Clear ≤ 0.016
Str/cc

Exceedance
0.016 Str/cc

Note: No on-site
activity 7/13-7/19

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Winconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
7/1/2021	<0.00090	<0.00050	0.00090
7/2/2021	<0.00090	<0.00090	<0.00090
7/5/2021	HOLIDAY		
7/6/2021	0.013	<0.0010	<0.0010
7/7/2021	0.018	0.00090	<0.00090
7/8/2021	0.025	0.0028	<0.00090
7/9/2021	0.0051	<0.00090	<0.00090
7/12/2021	0.0028	<0.00090	<0.00090
7/13/2021			
7/14/2021			
7/15/2021			
7/16/2021			
7/19/2021			

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Winconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
7/20/2021	<0.0010	<0.0010	N/A*
7/21/2021	<0.00090	<0.00090	N/A*
7/22/2021	<0.00090	<0.00090	<0.00090
7/23/2021	<0.00090	<0.00090	<0.00090
7/26/2021	0.0018	<0.00090	<0.00090
7/27/2021	<0.00090	0.00090	<0.00090
7/28/2021	<0.00090	<0.00090	<0.00090
7/29/2021	<0.0010	<0.00090	<0.00090
7/30/2021	<0.00090	<0.00090	<0.00090

JULY2021 NOA EXCEEDANCE

- Date: July 7, July 8 @ (Downwind Monitor)
- Cause: Site grading of parking lot
- Source: Parking lot grading on Connecticut Street near 26th Street.
- Action: Contractor increased water suppression through higher volume/frequency of watering disturbed soil while grading commencement on 7/7. 7/8 activities included placement of gravel rock which led to 7/8 exceedance. Gravel rock is now top soil in this location and is a Non – NOA soil.