

October 3 - October 7, 2022
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

10/3/22 – 10/7/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
10/3/2022	< 0.00090	< 0.00090	< 0.00090
10/4/2022	< 0.00090	< 0.00090	< 0.00090
10/5/2022	< 0.00090	< 0.00090	< 0.00050
10/6/2022	0.012	< 0.00090	0.0073
10/7/2022	0.0059	< 0.0010	< 0.0010

NOA reports
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

10/3/22 – 10/7/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report
Potrero Phase 2
2/21/22 - 2/25/22

監測結果
波特雷羅第二階段
2/21/22至 2/25/22

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
10/3/2022	0.013	0.017	0.015
10/4/2022	0.016	0.024	0.017
10/5/2022	0.012	0.018	0.013
10/6/2022	0.013	0.020	0.015
10/7/2022	0.010	0.014	0.011

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>