

February 6 - February 10, 2023
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

2/6/23 – 2/10/23: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
2/6/2023	< 0.0010	0.00090	<0.0010
2/7/2023	< 0.00090	< 0.00090	< 0.00090
2/8/2023	< 0.00090	< 0.00090	< 0.00090
2/9/2023	< 0.0010	< 0.0010	< 0.0010
2/10/2023	< 0.00090	< 0.00050	< 0.00090

NOA reports
posted @

<http://www.rebuildpotrero.com/airmonitoring>

NOA EXCEEDANCES - DETAILS

Date(s):

Source: None to Report

Action: N/A

2/6/23 – 2/10/23: PM10 / Dust Weekly REPORT

Dust Monitoring Report
Potrero Phase 2

監測結果
波特雷羅第二階段

Informe de monitoreo de
polvo
Potrero Fase 2

Clear $\leq 0.05 \text{ mg/m}^3$

安全
No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準
Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
2/6/2023	0.011	0.026	0.007
2/7/2023	0.022	0.023	0.017
2/8/2023	0.038	0.018	0.034
2/9/2023	0.042	0.022	0.035
2/10/2023	0.023	0.012	0.017

NOTE: Upwind monitor was removed from the upwind monitoring station without permission. Potrero monitoring consultants are currently retrieving a replacement upwind monitor

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>

PM-10 Exceedances - Details

Date(s):

Source: None to Report

Action: N/A