

**March 28 – April 1, 2022**  
**Weekly Air Monitor Report**  
**Potrero Phase 2 Infrastructure**

## MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

**Note: Any detection above an “action level” is investigated for cause and mitigated.**

## 3/28/22 – 4/1/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
3/28/2022	< 0.0010	0.0010	< 0.0010
3/29/2022	0.0020	< 0.00090	< 0.00090
3/30/2022	< 0.0010	< 0.00090	< 0.00090
3/31/2022	0.0019	0.0019	< 0.00090
4/1/2022	< 0.0010	0.00090	< 0.00090

NOA reports  
posted @

<http://www.rebuildpotrero.com/airmonitoring>

Note: 1/20- Rainouts witnessed. Filter overloaded resulting in N/A reading.

## 3/28/22 – 4/1/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report  
Potrero Phase 2  
2/21/22 - 2/25/22

監測結果  
波特雷羅第二階段  
2/21/22至 2/25/22

*Informe de monitoreo de  
polvo  
Potrero Fase 2*

Clear  $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance  $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM <sub>10</sub> (mg/m <sup>3</sup> )	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
<b>3/28/2022</b>	<b>0.007</b>	<b>0.013</b>	<b>0.018</b>
<b>3/29/2022</b>	<b>0.010</b>	<b>0.019</b>	<b>0.022</b>
<b>3/30/2022</b>	<b>0.011</b>	<b>0.020</b>	<b>0.022</b>
<b>3/31/2022</b>	<b>0.023</b>	<b>0.031</b>	<b>0.035</b>
<b>4/1/2022</b>	<b>0.030</b>	<b>0.036</b>	<b>0.040</b>

Dust Monitoring reports posted 粉塵報告公佈於 @

*Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>*