

**March 14 – March 18, 2022**  
**Weekly Air Monitor Report**  
**Potrero Phase 2 Infrastructure**

## MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

## 3/14/22 – 3/18/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
Exceedance > 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
3/14/2022	<b>0.0028</b>	<b>0.0038</b>	<b>&lt; 0.00090</b>
3/15/2022	<b>&lt; 0.00090</b>	<b>&lt; 0.00090</b>	<b>&lt; 0.00090</b>
3/16/2022	<b>0.0019</b>	<b>&lt; 0.0010</b>	<b>&lt; 0.0010</b>
3/17/2022	<b>0.0010</b>	<b>&lt; 0.0010</b>	<b>&lt; 0.0010</b>
3/18/2022	<b>0.0029</b>	<b>0.00090</b>	<b>&lt; 0.00090</b>

NOA reports  
posted @

<http://www.rebuildpotrero.com/airmonitoring>

Note: 1/20- Rainouts witnessed. Filter overloaded resulting in N/A reading.

## 3/14/22 – 3/18/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report  
Potrero Phase 2  
2/21/22 - 2/25/22

監測結果  
波特雷羅第二階段  
2/21/22至 2/25/22

Informe de monitoreo de  
polvo  
Potrero Fase 2

Clear  $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance  $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM <sub>10</sub> (mg/m <sup>3</sup> )	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
3/14/2022	0.021	0.021	0.026
3/15/2022	0.006	0.007	0.014
3/16/2022	0.021	0.025	0.027
3/17/2022	0.016	0.019	0.022
3/18/2022	0.013	0.015	0.022

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>