

January 16 - January 20, 2023
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

1/16/23 – 1/20/23: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
1/16/2023	Holiday	Holiday	Holiday
1/17/2023	< 0.00090	< 0.00090	< 0.0010
1/18/2023	< 0.00090	< 0.00090	< 0.00090
1/19/2023	< 0.00090	< 0.00090	< 0.00090
1/20/2023	< 0.00090	< 0.00090	< 0.00090

NOA reports
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

1/16/23 – 1/20/23: PM10 / Dust Weekly REPORT

Dust Monitoring Report
Potrero Phase 2

監測結果
波特雷羅第二階段

Informe de monitoreo de
polvo
Potrero Fase 2

Clear $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
1/16/2023	No Site Work Due to Rain		
1/17/2023	0.009	0.023	0.016
1/18/2023	0.014	0.015	0.029
1/19/2023	0.010	0.006	0.014
1/20/2023	0.007	0.004	0.013

NOTE: Upwind monitor was removed from the upwind monitoring station without permission. Potrero monitoring consultants are currently retrieving a replacement upwind monitor

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>