

May 2 – May 6, 2022
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

5/2/22 – 5/6/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
5/2/2022	< 0.00090	< 0.00090	< 0.00090
5/3/2022	0.00090	< 0.00090	< 0.00090
5/4/2022	< 0.0010	< 0.00090	< 0.0010
5/5/2022	0.0028	< 0.00090	< 0.00090
5/6/2022	0.0018	0.00090	< 0.00090

NOA reports
posted @

<http://www.rebuildpotrero.com/airmonitoring>

Note: 1/20- Rainouts witnessed. Filter overloaded resulting in N/A reading.

5/2/22 – 5/6/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report
Potrero Phase 2
2/21/22 - 2/25/22

監測結果
波特雷羅第二階段
2/21/22至 2/25/22

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
5/2/2022	0.007	0.008	0.009
5/3/2022	0.008	0.006	0.005
5/4/2022	0.019	0.018	0.017
5/5/2022	0.011	0.014	0.013
5/6/2022	0.006	0.007	0.011

Notes:

Daily Average $\leq 0.050 \text{ mg/m}^3$

Daily Average $> 0.050 \text{ mg/m}^3$

Dust Monitoring reports posted 粉塵報告公佈於 @
Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>