

November 7 - November 11, 2022
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

11/7/22 – 11/11/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
11/7/2022	0.0019	0.0058	< 0.0010
11/8/2022	0.0038	0.0010	< 0.0010
11/9/2022	< 0.00090	< 0.0010	< 0.0010
11/10/2022	0.0065	< 0.0010	< 0.0010
11/11/2022	0.0010	< 0.0010	< 0.0010

NOA reports
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

11/7/22 – 11/11/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report Potrero Phase 2

監測結果
波特雷羅第二階段

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
11/7/2022	0.007	0.005	0.005
11/8/2022	Site Shutdown Due to Rain		
11/9/2022	0.008	0.007	0.013
11/10/2022	0.012	0.010	0.017
11/11/2022	0.032	0.031	0.048

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>