

May 1 – May 5, 2023
Weekly Air Monitor Report
Potrero Phase 2
Infrastructure

WEEKLY AIR MONITORING RESULTS

BRIDGE Monitors for the Following:

Naturally Occurring Asbestos (NOA)
Particulates or PM10

Note: Any detection above the project action level is investigated and mitigation measures proposed.

5/1/23 – 5/5/23: NOA WEEKLY REPORT

Clear < 0.016 s/cc
Exceedance ≥ 0.016 s/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	s/cc	s/cc	s/cc
5/1/23	0.0027	<0.0009	<0.0009
5/2/23	0.0009	<0.0009	<0.0009
5/3/23	<0.0009	<0.0009	<0.0009
5/4/23	<0.0009	<0.0009	<0.0009
5/5/23	0.0009	0.0018	0.0009

NOA reports
posted @

<http://www.rebuildpotrero.com/airmonitoring>

5/1/23 – 5/5/23: NOA RESPONSE ACTIONS AND WEEKLY DATA SUMMARY

Date(s): No readings above the action level for the week of 5/1/23

Potential Source: NA

Response Action: NA

Weekly Data Summary: No detections of NOA above the action level.

5/1/23 – 5/5/23: PM10 WEEKLY REPORT

Dust Monitoring Report
Potrero Phase 2
5/1/23 - 5/5/23

監測結果
波特雷羅第二階段
5/1/23至 5/5/23

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear ≤ 0.05 mg/m³

安全

No supera los límites

Exceedance > 0.05 mg/m³

超出標準

Supera los límites

Date	Daily (24 Hr) Average in mg/m ³		
	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
5/1/23	0.019	0.006	0.007
5/2/23	0.017	0.004	0.003
5/3/23	0.018	0.001	0.003
5/4/23	0.024	0.015	0.005
5/5/23	0.026	0.010	0.006

Note: Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>