

April 11 – April 15, 2022
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

4/11/22 – 4/15/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
4/11/2022	< 0.0010	< 0.00090	< 0.0010
4/12/2022	< 0.0010	< 0.00090	< 0.0010
4/13/2022	< 0.0010	< 0.00090	0.0019
4/14/2022	0.0028	< 0.00090	< 0.00090
4/15/2022	0.0018	< 0.00090	0.00090

NOA reports
posted @

<http://www.rebuildpotrero.com/airmonitoring>

Note: 1/20- Rainouts witnessed. Filter overloaded resulting in N/A reading.

4/11/22 – 4/15/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report
Potrero Phase 2
2/21/22 - 2/25/22

監測結果
波特雷羅第二階段
2/21/22至 2/25/22

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全
No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準
Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
4/11/2022	0.010	0.022	0.026
4/12/2022	0.011	0.023	0.027
4/13/2022	0.010	0.022	0.024
4/14/2022	0.012	0.022	0.027
4/15/2022	0.008	0.018	0.025

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>