

December 26 - December 30, 2022
Weekly Air Monitor Report
Potrero Phase 2 Infrastructure

MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

Note: Any detection above an “action level” is investigated for cause and mitigated.

12/26/22 – 12/30/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
12/26/2022	Holiday	Holiday	Holiday
12/27/2022	< 0.0010	< 0.00090	0.0038
12/28/2022	< 0.0010	< 0.00090	< 0.0010
12/29/2022	< 0.0010	< 0.0010	< 0.00090
12/30/2022	<0.0009	<0.0009	<0.0010

NOA reports
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

12/26/22 – 12/30/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report
Potrero Phase 2

監測結果
波特雷羅第二階段

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM ₁₀ (mg/m ³)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
12/26/2022	Observance of Christmas Holiday		
12/27/2022	0.021	0.026	-
12/28/2022	0.033	0.035	-
12/29/2022	0.009	0.008	-
12/30/2022	0.010	0.010	-

Notes:

Daily Average $\leq 0.050 \text{ mg/m}^3$

Daily Average $> 0.050 \text{ mg/m}^3$

NOTE: Upwind monitor was removed from the upwind monitoring station without permission. Potrero monitoring consultants are currently retrieving a replacement upwind monitor

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>