

Rebuild Potrero: Dust Monitoring Report

October 2018

Dust Monitoring Results



	PM-1	PM-2			PM-1	PM-2
9/1/2018	Clear	Clear		9/17/2018	Clear	Clear
9/2/2018	Clear	Clear		9/18/2018	Clear	Clear
9/3/2018	Clear	Clear		9/19/2018	Clear	Clear
9/4/2018	Clear	Clear		9/20/2018	Clear	Clear
9/5/2018	Clear	Clear		9/21/2018	Exceedance	Clear
9/6/2018	Clear	Clear		9/22/2018	Clear	Clear
9/7/2018	Clear	Clear		9/23/2018	Clear	Clear
9/8/2018	Clear	Clear		9/24/2018	Clear	Clear
9/9/2018	Clear	Clear		9/25/2018	Clear	Clear
9/10/2018	Clear	Clear		9/26/2018	Clear	Clear
9/11/2018	Clear	Clear		9/27/2018	Clear	Clear
9/12/2018	Clear	Clear		9/28/2018	Clear	Clear
9/13/2018	Clear	Clear		9/29/2018	Clear	Clear
9/14/2018	Clear	Clear		9/30/2018	Clear	Clear
9/15/2018	Clear	Clear				
9/16/2018	Clear	Clear				

NOA Monitoring Results

	BLKX - 1	BLKX - 2		BLKX - 1	BLKX - 2
9/1/2018				9/17/2018	
9/2/2018				9/18/2018	
9/3/2018				9/19/2018	
9/4/2018				9/20/2018	
9/5/2018				9/21/2018	
9/6/2018				9/22/2018	
9/7/2018				9/23/2018	
9/8/2018				9/24/2018	
9/9/2018				9/25/2018	
9/10/2018				9/26/2018	
9/11/2018				9/27/2018	
9/12/2018				9/28/2018	
9/13/2018				9/29/2018	
9/14/2018				9/30/2018	
9/15/2018					
9/16/2018					

Clear

Exceedance