

March 2021 Air Monitoring Report


Clear
Exceedance

- No Naturally Occurring Asbestos (NOA) exceedances in March
- NOA monitoring results available @ www.RebuildPotrero.com/airmonitoring

	TEM-CARB (Str/cc)
3/9/2021	
3/10/2021	
3/11/2021	
3/12/2021	
3/15/2021	
3/16/2021	
3/17/2021	
3/18/2021	
3/19/2021	
3/22/2021	
3/23/2021	
3/24/2021	
3/25/2021	
3/26/2021	
3/29/2021	
3/30/2021	
3/31/2021	
4/1/2021	
4/2/2021	

Air Monitor Stations





Air Monitor locations:

Air monitoring stations are installed at the locations indicated in red



- **Visible trackout control**
- **Onsite - 15 MPH vehicle max speed**
- **Offsite soil transport – Soil Wetted, covered**



Mitigation strategies to reduce air quality impacts

Soil Stabilizer



Soil Wetting



Soil Tarping



Mitigation strategies to reduce air quality impacts