

# Rebuild Potrero: Dust Monitoring Report

September 2018

# Dust Monitoring Results



	PM-1	PM-2			PM-1	PM-2
8/1/2018	Clear	Clear		8/17/2018	Clear	Clear
8/2/2018	Clear	Clear		8/18/2018	Clear	Clear
8/3/2018	Clear	Clear		8/19/2018	Clear	Clear
8/4/2018	Clear	Clear		8/20/2018	Clear	Clear
8/5/2018	Clear	Clear		8/21/2018	Clear	Clear
8/6/2018	Clear	Clear		8/22/2018	Clear	Clear
8/7/2018	Clear	Clear		8/23/2018	Clear	Clear
8/8/2018	Clear	Clear		8/24/2018	Clear	Clear
8/9/2018	Clear	Clear		8/25/2018	Clear	Clear
8/10/2018	Clear	Clear		8/26/2018	Clear	Clear
8/11/2018	Clear	Clear		8/27/2018	Clear	Clear
8/12/2018	Clear	Clear		8/28/2018	Clear	Clear
8/13/2018	Clear	Clear		8/29/2018	Exceedance	Clear
8/14/2018	Clear	Clear		8/30/2018	Clear	Clear
8/15/2018	Clear	Clear		8/31/2018	Clear	Clear
8/16/2018	Clear	Clear				

# NOA Monitoring Results

	BLKX - 1	BLKX - 2			BLKX - 1	BLKX - 2
8/1/2018				8/17/2018		
8/2/2018				8/18/2018		
8/3/2018				8/19/2018		
8/4/2018				8/20/2018		
8/5/2018				8/21/2018		
8/6/2018				8/22/2018		
8/7/2018				8/23/2018		
8/8/2018				8/24/2018		
8/9/2018				8/25/2018		
8/10/2018				8/26/2018		
8/11/2018				8/27/2018		
8/12/2018				8/28/2018		
8/13/2018				8/29/2018		
8/14/2018				8/30/2018		
8/15/2018				8/31/2018		
8/16/2018						

Clear

Exceedance