

**August 1 – August 5, 2022**  
**Weekly Air Monitor Report**  
**Potrero Phase 2 Infrastructure**

## MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

**Note: Any detection above an “action level” is investigated for cause and mitigated.**

## 8/1/22 – 8/5/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc
Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
8/1/2022	0.0020	0.012	< 0.00090
8/2/2022	0.0046	0.010	< 0.00090
8/3/2022	0.00090	0.0027	< 0.00090
8/4/2022	< 0.0010	0.0020	< 0.0010
8/5/2022	< 0.00090	< 0.00090	< 0.00090

NOA reports  
posted @

<http://www.rebuildpotrero.com/airmonitoring>

## 8/1/22 – 8/5/22: PM10 / Dust Weekly REPORT

Dust Monitoring Report  
Potrero Phase 2  
2/21/22 - 2/25/22

監測結果  
波特雷羅第二階段  
2/21/22至 2/25/22

Informe de monitoreo de  
polvo  
Potrero Fase 2

Clear  $\leq 0.05 \text{ mg/m}^3$

安全  
No supera los límites

Exceedance  $> 0.05 \text{ mg/m}^3$

超出標準  
Supera los límites

Daily Average PM <sub>10</sub> (mg/m <sup>3</sup> )	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
8/1/2022	0.014	0.012	0.017
8/2/2022	0.014	0.004	0.016
8/3/2022	0.009	0.004 *	0.011
8/4/2022	0.020	0.014	0.021
8/5/2022	0.009	0.001	0.012

Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>