

**January 23 - January 27, 2023**  
**Weekly Air Monitor Report**  
**Potrero Phase 2 Infrastructure**

## MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

**Note: Any detection above an “action level” is investigated for cause and mitigated.**

# 1/23/23 – 1/27/23: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc  
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
1/23/2023	< 0.00090	0.00090	< 0.00090
1/24/2023	< 0.00090	< 0.00050	< 0.00090
1/25/2023	< 0.00090	< 0.0010	< 0.0010
1/26/2023	< 0.0010	< 0.00090	< 0.0010
1/27/2023	< 0.00090	< 0.00090	< 0.00090

NOA reports  
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

# 1/23/23 – 1/27/23: PM10 / Dust Weekly REPORT

Dust Monitoring Report  
Potrero Phase 2

監測結果  
波特雷羅第二階段

*Informe de monitoreo de  
polvo  
Potrero Fase 2*

Clear  $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance  $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Daily Average PM <sub>10</sub> (mg/m <sup>3</sup> )	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
1/23/2023	0.012	0.004	0.024
1/24/2023	0.015	0.017	0.025
1/25/2023	0.032	0.028	0.042
1/26/2023	0.013	0.011	0.022
1/27/2023	0.013	0.022	0.015

NOTE: Upwind monitor was removed from the upwind monitoring station without permission. Potrero monitoring consultants are currently retrieving a replacement upwind monitor

Dust Monitoring reports posted 粉塵報告公佈於 @

*Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>*