

**July 3 – July 7, 2023 Weekly
Air Monitor Report
Potrero Phase 2
Infrastructure**

WEEKLY AIR MONITORING RESULTS

BRIDGE Monitors for the Following:

Naturally Occurring Asbestos (NOA)
Particulates or PM10

Note: Any detection above the project action level is investigated and mitigation measures proposed.

7/3/23 – 7/7/23: NOA WEEKLY REPORT

Clear < 0.016 s/cc
Exceedance ≥ 0.016 s/cc

	Location 1 Upwind: Wisconsin St Perimeter	Location 2 Downwind: Connecticut St Perimeter	Location 3 Crosswind: 25th St Perimeter
Date	s/cc	s/cc	s/cc
7/3/23	0.0009	<0.0009	0.0009
7/4/23	Holiday, No Work		
7/5/23	<0.0009	0.0080	0.0018
7/6/23	<0.0009	0.0510	0.0072
7/7/23	<0.0009	0.0064	0.0082

NOA reports
posted @

<http://www.rebuildpotrero.com/airmonitoring>

7/3/23 – 7/7/23: NOA RESPONSE ACTIONS AND WEEKLY DATA SUMMARY

Date(s): One reading above the action level for the week starting 7/3/23: Crosswind monitor on July 6, 0.0510 s/cc

Potential Source: Loading, hauling, and re-stockpiling surplus soil from Parcel B to Parcel A.

Response Action: Track-walk and nominally compact new stockpile to await re-use or disposal. This area will be treated with bonded fiber matrix in the near future.

Weekly Data Summary: All other readings below the action level.

7/3/23 – 7/7/23: PM10 WEEKLY REPORT

Dust Monitoring Report
Potrero Phase 2
7/3/23 - 7/7/23

監測結果
波特雷羅第二階段
7/3/23至7/7/23

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear ≤ 0.05 mg/m³

安全

No supera los límites

Exceedance > 0.05 mg/m³

超出標準

Supera los límites

Date	Daily (24 Hr) Average in mg/m ³		
	Monitor 1 (Upwind)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)
7/3/23	0.009	0.008	0.011
7/4/23	0.016	0.014	0.017
7/5/23	0.008	0.008	0.009
7/6/23	0.004	0.004	0.004
7/7/23	0.005	0.007	0.008

Note: Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>