

**November 21 - November 25, 2022**  
**Weekly Air Monitor Report**  
**Potrero Phase 2 Infrastructure**

## MONTHLY AIR MONITORING RESULTS:

BRIDGE monitors 2 separate readings:

- Naturally Occurring Asbestos (NOA)
- Dust

**Note: Any detection above an “action level” is investigated for cause and mitigated.**

# 11/21/22 – 11/25/22: NATURALLY OCCURRING ASBESTOS (NOA) REPORT

Clear < 0.016 Str/cc  
 Exceedance ≥ 0.016 Str/cc

	Location 2 Downwind: Connecticut St Interior Perimeter	Location 3 Crosswind: 25th St Side Interior Perimeter	Location 1 Upwind: Wisconsin St Interior Perimeter
Date	str/cc	str/cc	str/cc
11/21/2022	< 0.0010	< 0.0010	< 0.00090
11/22/2022	< 0.0010	0.00090	< 0.0010
11/23/2022	< 0.00090	0.0010	< 0.00090
11/24/2022	Holiday		
11/25/2022	Holiday		

NOA reports  
 posted @

<http://www.rebuildpotrero.com/airmonitoring>

# 11/21/22 – 11/25/22: PM10 / Dust Weekly REPORT

## Dust Monitoring Report Potrero Phase 2

監測結果  
波特雷羅第二階段

*Informe de monitoreo de  
polvo  
Potrero Fase 2*

Clear  $\leq 0.05 \text{ mg/m}^3$

安全  
No supera los límites

Exceedance  $> 0.05 \text{ mg/m}^3$

超出標準  
Supera los límites

## PM<sub>10</sub> Monitoring Results

Potrero Phase 2

11-21-2022 through 11-25-2022

Daily Average PM <sub>10</sub> (mg/m <sup>3</sup> )	Monitor 2 (Downwind)	Monitor 3 (Crosswind)	Monitor 1 (Upwind)
11/21/2022	0.024	0.021	0.027
11/22/2022	0.039	0.040	0.046
11/23/2022	0.038	0.039	0.046
11/24/2022	Site Shutdown - Holiday		
11/25/2022	Site Shutdown - Holiday		

Notes:

Daily Average  $\leq 0.050 \text{ mg/m}^3$

Daily Average  $> 0.050 \text{ mg/m}^3$

Dust Monitoring reports posted 粉塵報告公佈於 @

*Los informes del polvo se publican en* <http://www.rebuildpotrero.com/airmonitoring>