

**August 7 – August 11,
2023 Weekly Air
Monitor Report
Potrero Phase 2
Infrastructure**

WEEKLY AIR MONITORING RESULTS

BRIDGE Monitors for the Following:

Naturally Occurring Asbestos (NOA)
Particulates or PM10

Note: Any detection above the project action level is investigated and mitigation measures proposed.

8/7/23 – 8/11/23: NOA WEEKLY REPORT

Clear < 0.016 s/cc
Exceedance ≥ 0.016 s/cc

	Location 1 Upwind: Wisconsin St Perimeter	Location 2 Downwind: Connecticut St Perimeter	Location 3 Crosswind: 25th St Perimeter
Date	s/cc	s/cc	s/cc
8/7/23	<0.0009	sample missing	<0.0009
8/8/23	0.0110	0.0390	0.0490
8/9/23	<0.0009	0.0009	0.0009
8/10/23	<0.0010	0.0058	0.0019
8/11/23	0.0030	0.0039	0.0039

NOA reports
posted @

<http://www.rebuildpotrero.com/airmonitoring>

8/7/23 – 8/11/23: NOA RESPONSE ACTIONS AND WEEKLY DATA SUMMARY

Date(s): Two readings above the action level for the week starting August 7: Crosswind and downwind monitor on August 8 .

Potential Source: Moving soil from Block A to Block B, placing soil around the foundation on Block B.

Response Action: Dedicate a laborer with a fire hose to the soil loading process whenever this work is active.

Weekly Data Summary: All other readings below the action level.

8/7/23 – 8/11/23: PM10 WEEKLY REPORT

Dust Monitoring Report
Potrero Phase 2
8/7/23 - 8/11/23

監測結果
波特雷羅第二階段
7/3/23至7/7/23

*Informe de monitoreo de
polvo
Potrero Fase 2*

Clear $\leq 0.05 \text{ mg/m}^3$

安全

No supera los límites

Exceedance $> 0.05 \text{ mg/m}^3$

超出標準

Supera los límites

Date	Daily (24 Hr) Average in mg/m^3		
	Monitor 1 (Upwind)	Monitor 2 (Downwind)	Monitor 3 (Crosswind)
8/7/23	0.010	0.011	0.013
8/8/23	0.012	0.001	0.016
8/9/23	0.003	0.002	0.026
8/10/23	0.002	0.011	0.023
8/11/23	0.006	0.006	0.007

Note: Dust Monitoring reports posted 粉塵報告公佈於 @

Los informes del polvo se publican en <http://www.rebuildpotrero.com/airmonitoring>